

## Technician Bulletin—Troubleshooting for CK2555 & CK2575

### Passthrough Dishwashers

A common problem, that our customers report, is due to poor maintenance of the air trap.

The air trap is located on the back wall inside the washing chamber (Pic 1). A build up of dirt behind the plastic protection means the machine may either over or under fill. (Pic 2)

**This problem ISN'T covered by our warranty due to lack of maintenance.**

To solve the problem simply remove the 2 metal nuts (Pic 3), give the area a quick wipe and replace. Once replaced remove the hexagonal valve, wash & replace. PLEASE DO NOT REMOVE BOTH AT THE SAME TIME (Pic 4). This only needs completing monthly.

Pic 1



Pic 2



Pic 3



Pic 4

